

2006 Lear 60-306  
N869AV

Ettinger Aviation Services, LLC  
Bob Ettinger 908-619-9264  
EASLLC@earthlink.net



## Features

- ADS-B Out – July 2018
- TCAS 7.1 – March 2018
- Interior Refurbishment - June 2018
- New Exterior Paint - July 2016
- GoGo ATG-2000
- Dual Universal UNS-1Ew with WAAS/LPV
- 12 Year Inspection c/w July 2018
- A1-A6 c/w February 2019 / B1-B6 Inspection c/w July 2018
- 3000 Landing Inspection c/w July 2018
- Airshow 400, DVD Player, 10 Disc CD Player
- 8 Passenger Interior with Belted Lav
- FAR 135 Compliant
- No Damage History



## Specifications (10/1/18)

### Log Summary

Total Time Airframe 5,320

Total Landings 2930

### Engines

Engine #1 S/N PCE-CA0470

Total Time 5254

Cycles 2,890

Engine #2 S/N PCE-CA0471

Total Time 5254

Cycles 2,890

Engines Enrolled On Pratt & Whitney ESP

APU – Not Installed



## Avionics

<b>Lear 60-306</b>	<b>N869AV</b>
Avionics Package:	Proline IV
Comm Radios:	Dual Collins VHF-422C w/8.33 Spacing
Nav Radios:	Dual Collins VIR-432
HF Radios	Dual King KTR-953 w/ SELCAL
FMS	Dual Universal UNS-1Ew With WAAS/LPV
Wx Radar	Collins RTA-854
Transponders	Dual TDR-94D
TAWS	Honeywell EGPWSW w/windshear detection
TCAS	TCAS II w/Change 7.1
ADF	Collins 462 ADF
DME	Dual Collins DME-442



## Interior

- Eight (8) passenger executive interior featuring Forward, side-facing 2-place divan opposite single seat, Mid 4-place club and Aft belted lav & extended baggage area. Forward galley featuring dual hot liquid containers & microwave oven. Two pullout executive tables, forward pocket doors, left & right rear pyramid cabinets.
- Collins Airshow 400, forward 15.1-inch video monitor, aft 10.4-inch video monitor, DVD player, CD player w/10-disc CD changer
- 110 Volt outlets in cabin & cockpit.



Lear 60-306

N869AV



Lear 60-306

N869AV





Lear 60-306

N869AV

